




Product Assembly Instructions


LCBASOBR



D: Hex Nut x8



E: Washer x8



F: F-Bolt 6*20 x2



G: Spanner x1



H: Allenkey x1

A: Main Frame x1

B: Leg x4

C: Leg x1

STEP 1

