












<p>ITEM: 1670-GB</p>	<p>① SEAT</p> 	<p>② GAS LIFT</p> 	<p>③ COLUMN</p> 	<p>④ BASE</p> 	<p>⑤ Screw M8x30 3Pcs</p> 	<p>⑥ Screw M6x30 2Pcs</p> 	<p>⑦ Spanner Φ4x1Pcs</p> 	<p>⑧ Spanner Φ5x1Pcs</p> 	<p>⑨ Screw M6x20 2Pcs</p> 
--	--	---	---	---	---	---	---	---	--

STEP A




STEP B

Please fix front two screws first



STEP C



STEP D

